


SHIVERS


PRIMARY ADDITIONAL EQUIPMENT PANEL PARTS MANUAL



**Primary Additional Equipment Panel
1 Phase, 3-5 HP**

PAEP1P5


598A-001A



**Primary Additional Equipment Panel
1 Phase, 7.5 - 10 HP**

PAEP1P10


598B-001A



Primary Additional Equipment Panel
3 Phase, 3 - 10 HP

PAEP3P10

598C-001A



SINGLE & THREE PHASE

Shivvers Part #	Contactor # of Poles	Overload Only Part #	Overload Amp Setting	3 PH MOTOR HP			1 PH Motor HP 240V
				208/230V	460V	575V	
641Y-001A (40 Amp Contactor)	4	E-6516	3-12	2	2	3	
				3	3	5	
					5	7.5	2
641X-001A (40 Amp Contactor)	4	E-6517	10-40	5	7.5	15	3
				7.5	10		5
				10	15		
641Z-001A (60 Amp Contactor)	3	E-6518	25-100	15			7.5
							10
							12.5
							15