


# 653-241A INSTRUCTIONS SWIVEL MOUNT KIT



SHIVERS MANUFACTURING, INC  
CORYDON, IOWA, USA  
641-872-1005  
[www.shivers.com](http://www.shivers.com)

P-12553  
8/7/2014

# GRAIN SPREADER SWIVEL MOUNT ASSEMBLY

Parts List			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	3	653-233P	Swivel Mount Bracket
2	3	653-237P	Swivel Mount Plate
3	3	653-238P	Bracket Arm
4	3	653-236W	Eyebolt Weldment
5	6	F-1464	1/2" Lockwasher
6	36	F-1009-03	3/8" Flat Washer
7	18	F-1239	3/8 Locknut
8	18	F-1307	3/8-16 x 1 1/4" Capscrew
9	6	F-1011-05	Nut, Hex 1/2-13
10	9	F-1011-06	Nut, Hex 5/8-11
11	6	F-1526	1/2-13 x1-1/2" Capscrew
12	3	F-1651	Lock Washer, 5/8 Split
13	12	F-1009-05	1/2" Flat Washer
14	3	653-252P	Reinforcement Strap

